

Product: i75/9d24 top front cover

Purpose: Procedure to replace the top front cover on the i75/9d24 handset

Date: 4/30/2008

Top Front Cover Replacement Procedure

The i75/9d24 handset can be equipped with an alternative colored top front cover, purchased separately. To replace the existing top front cover on the handset, perform the following steps.

1. With a Torx (T6) screw driver, release the two screws at top on the handset and lift off the top front, see figure 1 and figure 2.




Figure 1 – Release the two screws at top on the handset.

Technical Service Bulletin

ascom

Product: i75/9d24 top front cover

Purpose: Procedure to replace the top front cover on the i75/9d24 handset

Date: 4/30/2008




Figure 2 – Lift off the top front cover

2. Mount the new top front cover on the handset and fasten it with two screws, see figure 3, figure 4 and figure 5.

Technical Service Bulletin

ascom

Product: i75/9d24 top front cover

Purpose: Procedure to replace the top front cover on the i75/9d24 handset

Date: 4/30/2008




Figure 3 – Put the new top front in place on the handset.




Figure 4 – Make sure that the top front is well mounted. Press with your thumbs on the top front as shown in figure 4 and figure 5 (below).

Technical Service Bulletin

ascom

Product: i75/9d24 top front cover

Purpose: Procedure to replace the top front cover on the i75/9d24 handset

Date: 4/30/2008




Figure 5 – Fasten the top front with two screws, utilizing a T6 torque driver set to 14Ncm.

Additional Information

If you have any questions about this bulletin, please contact Ascom Technical Services at 1-877 71ASCOM (1-877-712-7266) option 3.